

भारत सरकार GOVERNMENT OF INDIA केन्द्रीय लोक निर्माण विभाग



CENTRAL PUBLIC WORKS DEPARTMENT

कार्यपालक अभियंता का कार्यालय

कालिकट केन्द्रीय मंडल

Office of the Executive Engineer Calicut Central Division M S Baburaj Road, Kallai Calicut- 673 003

एम एस बाबुराज रोड, कल्लाई, कालिकट

स: 23(89)/	का के म	/2021/हि/	485
------------	---------	-----------	-----

सेवा में

The Principal, Kendriya Vidyalaya No.1, East Hill, Kozhikode-673005.

महोदय,

विषय: Safety and Security Certificate of the Kendriya Vidyalaya and Boundary wall etc. – reg.

संदर्भ: Lr. No. F.44/KVK-1/E.H/2021-22 dated: 09.07.2021.

The Kendriya Vidyalaya No.1 building at East Hill was inspected by the undersigned and it is certified that the following buildings are **safe and fit for conducting classes**.

1) The Vidyalaya Annex Building where primary and secondary classes are conducted.

2) PTA Block and MP Block where senior Secondary class are conducted.

In this regard, it is pointed out that the buildings in general need proper periodical maintenances including cleaning of open terraces from dust, dried leaves, small plants etc. Internal and external painting of walls is also needed to be carried out at the required frequencies.

केन्दीय लोक निम कल्लाई, कालिकट

प्रतिलिपिः-

(1) The Assistant Engineer, CCSD-I, CPWD Calicut for information with reference to the Lr. No. F.44/KVK-1/E.H/2021-22 dated; 09.07.2021.

कार्यपालक अभियंता